

The background of the image is a close-up, slightly blurred view of the American flag, showing the stars and stripes. The OSHA logo is prominently displayed in the center. The letter 'O' is a large, stylized circle with a blue outer ring and a grey inner ring. The letters 'S', 'H', and 'A' are white with a 3D effect and a drop shadow. The 'I' is also white but appears as a vertical bar.

**OSHA**

adds value to business,  
work and life.

# 1910.22 and 1910.23 OSHA Citations for 138x

Marianne McGee  
April 2007

# Recordkeeping - 1904

- Log of injuries was not maintained
- Fatality was not reported within 8 hours
- Annual summary was not completed

# Housekeeping – 1910.22

- Workroom floors were not maintained in a clean and dry condition.

# Floor Opening – 1910.23(a)

- Ladderway floor opening was not guarded by a standard railing on all exposed sides.
- Hatchway (or chute) opening was not guarded by a hinged cover.
- Floor opening was not guarded by a standard railing.
- Door opening onto a stairway reduced platform width to less than 20 inches

# Open-sided Floors, Platforms, and Runways - 1910.23(c)

- Open-sided floor or platform 4 feet or more above ground level was not guarded by a standard railing.
- Runway 4 feet or more above floor level was not guarded by a standard railing.
- Open-side floor adjacent to dangerous equipment was not guarded by a standard railing and toeboard.

# Stairway Railings and Guards – 1910.23(d)

- Stairways less than 44 inches wide having one open side did not have standard stair railings.
- Stairways less than 44 inches wide having both sides open did not have standard stair railings one each side.

# Fixed Industrial Stairs – 1910.24

- Stair treads were not slip-resistant and of uniform rise height and tread.
- Stairway platform was less than the width of the stairway and less than a minimum of 30 inches in length in the direction of travel.
- Standard railings were not provided on open-sides of stairways. Handrails must be provided on closed stairways.

# Portable Metal Ladders – 1910.26

- Ladder was not placed at correct angle, base shall be placed  $\frac{1}{4}$  distance of the working length from the vertical wall.
- For a 12 foot ladder, the base shall be 3 feet from the wall.

# Fixed Ladders – 1910.27

- Side rails of ladder extension did not extend 3.5 feet above landing.
- Ladders were not maintained in a safe condition.

The background of the image is a close-up, slightly blurred view of the American flag, showing the stars and stripes. The OSHA logo is centered in the upper half of the image. The letter 'O' is a large, stylized circle with a blue outer ring and a grey inner ring. The letters 'S', 'H', and 'A' are white with a 3D effect and a drop shadow. The text 'OSHA' is in a large, bold, serif font.

**OSHA**

adds value to business,  
work and life.